

File

2 sec. save constant
 1x recall constant
 2x history (1-20)
CLEAR OFF + 2 sec. delete history

Horizontal Measurement

1x → horizontal measurement permanent on
 2x → horizontal measurement off

1x 2 sec.

1x 2 sec.


1x 2 sec.

2x 2 sec.

Menu

2 sec. 1.1 2.1 3.1 4.1 5.1 6.1 7.1
 → MENU → MENU → MENU → MENU → MENU → MENU → MENU

+ or - changes settings in submenu
 = MENU 2 sec. saves all changed settings
CLEAR OFF exit menu without changes



- | | |
|-----------------------------|-----------------------|
| 1 ON/DIST
(on/measuring) | 8 Functions |
| 2 Smart Horizontal Mode | 9 Timer |
| 3 Plus (+) | 10 2nd for navigation |
| 4 Minus (-) | 11 Menu/equal |
| 5 Area/volume | 12 Clear/OFF |
| 6 Storage/Memory | 13 Bluetooth® |
| 7 Reference | |

- when it has to be **right**

Leica
Geosystems



1x → ON



2 sec. → OFF



1x



2nd






Bluetooth® on



1x send



**2 sec.
send all**



Laser class 2 in acc. to IEC 60825-1

www.disto.com



SAP.No. 776756a

